Verizon New England Inc. d/b/a Verizon New Hampshire

State of New Hampshire

Docket No. DM 05-172

Respondent: Marianne Ryan

Title: Director - Construction

REQUEST: New Hampshire Utilities Commission Staff, Set 1

DATED: November 29, 2005

ITEM: Staff 1-17 How are field personnel notified of potential hazardous pole

conditions? Is the B and C pole tag method employed?

ERRATA Field personnel are notified of hazardous pole conditions by utilizing the B and C pole tag method. The B tag has a white

arrow on a red background and is placed on a pole that is defective but not requiring immediate replacement. The C tag has an X inscribed in a circle that indicates the pole requires immediate replacement. When found in the field, these poles are communicated to the foreman for review and forwarded to

engineering for an immediate work order to replace.

VZ #17E